Approved ar Release 2001/07/28 ↑ © AFRDP 75906446R00010 €200046-0

FILE INFO

17.00	REPRODUCTION PROHIBITED		25 Ray 14 0	
ACTION COLL O COL	6	11	16	
2	7	12	17	
3	8	13	18	
4	9	14	19	
5	1ø	15	2ø	

25X1A

S E C R E T 251635Z APR 74 CITE

IMMEDIATE

INFO PRIORITY

25X1A ATTN:

- 1. HAVE HW-28 PRINTER FAILURE WITH SYMPTOMS AS FOLLOWS: USING TEXT-RANDOM LINE FEED FUNCTIONS OCCUR. USING RY-TAPE COPIES 95
 PERCENT OK, FOX TAPE LINE FEEDS ON RANDOM CHARACTERS EXCEPT RY'S.
- 2. PLEASE ADVISE BEST ESTIMATE OF PROBLEM AND HOW RESOLVE. PLEASE USE TERMINOLOGY USED IN TTY MANUAL AS NON-WIRE TECHS HAVE DIFFICULTY UNDERSTANDING/IDENTIFYING PARTS.
- 3. REQUEST FORWARD SPARE PRINTER SOONEST. PRESENT AND PROSPEC-TIVE WORKLOAD DEMANDS TWO HW-28'S IN OPERATION SIMULTANEOUSLY.
- ANY ASSIST YOU CAN OFFER TO EXPADITE PRINTER WILL BE APPRECIATED. E-2 IMPDET

SECRET

BT

25X1A

